



*Wile in the Rain*<sup>®</sup>  
ALL-WEATHER WRITING PAPER

## CONTENTS

1 Name	2 Address	3 Phone	4 Project	5	6
Clear Vinyl Protective Slipcovers (Item No. 30) are available for this style of notebook Helps protect your notebook from wear & tear. Contact your dealer or the J. L. Darling Corporation					

**Clear Vinyl Protective Slipcovers (Item No. 30) are available for this style of notebook. Helps protect your notebook from wear & tear. Contact your dealer or the J.L. Darling Company.**

Helps protect your notebook from wear & tear. Contact your dealer or the J. L. Darling Corporation.

Ron of Cascade Metals  
was given my card w/ my  
Cell # on back on 2/11 and I  
told him to call me if  
he was concerned, when I asked  
him on 2/20 why he didn't  
call me about the injury or  
his concern he said he thought  
about it, but didn't.

Spoke <sup>phone</sup> with Dennis @  
by phone 2:00 pm CACY.  
had been taken to occupational  
Health to be checked out. It  
was a chemical burn, could  
not determine as it was acid  
~~or~~ base. Some concern if it  
was a base due to complete  
with healing process. They will  
contact OSHA and filed  
a report.

Did site walk and wanted  
to interview Cascade Metals  
+ NRC rep @ approve 12:30 p  
but they left the site for  
the day.

Times I was assured that  
2/11 is when I discovered  
that ~~at~~ Ellis had sent NRC  
away

Times I was assured that  
the acid, base + AC Diner  
had been cleaned:  
Jonathan S. 4/2/20 by phone  
upon completion  
of tank form

Ferry Street Revelation  
Numerous times Beyond  
Attention

Workplan

5

~~Flush existing pipes~~  
Strategy + plans for Vessels  
being decommissioned.

Schedule

Discuss pipe scrapping / disposal  
Check the AC Tank for  
no pose

Rationale for VAO

- ① Un requested injuries/exposures
- ② Statement indicating that chem lines had been drained but not rinsed KOH incident of (2/m)
- ③ Statements received from both Scappers + NRC that the contents of a 5K tank make as acrylic containment had been released to City Storm water System who concurrence from city.
- ④ NRC/Rivercity request to be on site for safety of scrapping crew by my estimation they failed.
- ⑤ Content of ~~the~~ material collected from pipes indicated later to have

flushing in adequate/retest?

- ⑥ Inconsistent information, validation of work completed when it was not, lack of capacity to understand extent of work, and Lack of concern on financial matters (Lien, bauler) on the part of the key contractor, River City Y.

- ⑦ Veiled ~~then~~ threat "you'll be sorry" from NRC to cascade, "Tell the govt. <sup>OK</sup>"
- ⑧ Stop ~~y~~ House keeping/E pipe breaking.

- ⑨ Have lost confidence in NRC's capabilities when ~~was~~ not strictly overseen @ this site

Rita in the Rain

## Absorbent Prop Lead Rationale

- ① Have worked w NRC for almost 14 years, and they already had comprehensive closure plan for Queen.
- ② Motivated property owner

- ③ NRC already on the ground at site.

*Rita deRice*

1/28

11

Got Cody in Bucket Wagon  
grab by Anticimex from the  
Upper scaffolding.

Jeff from River City

1. FI D Screening Back Side  
1 ppm above B
2. Graph Coagomer + Near  
graph reactor ~~2 ppm~~ > Bg  
Photo #1 \* 10:57 AM
3. Acryl/o Mixer Pump 10 ppm  
photo#2 10:57  
photo#3 10:57 Activated starch
4. Starch + Covic Slurry Mix pump  
Bg Photo#4 11:00 am
5. Yellow Pipe SW corner Tank Farm  
Bg Photo #5 11:02 am
6. Starch Slurry line entering Blue  
Starch Reactor Photo #6 11:04 a  
Bg  
\* Camera date stamp & the photo

## #12 Activated Star ch

rector Tank entrance  
Outflow BG photo #7  
#8 is off tank 11:06

#8 Acyllo Pump Dis connected  
Upper scaffolding Tank Farm  
20 ppm #9 11:14

#9 North Acyllo cab yellow pipe ND  
Photo #10 11:15

#10 West " " ND  
Attached to #11 11:17a  
#11 South " " orange  
pneumatic pump Spray  
Photo #12 11:18a

#12 Acyllo product Line  
north side inner + outer  
pipe ND Photo #13 11:19.

#13 Acyllo Exhaust pipe  
Above south cabinet  
ND Photo #14 11:20

#14 Far Southern Cabinet Attached to tank, will sample 31 in level B Photo #15 11:24a	#15 Granular Activated carbon vessels 163 ppm Photo #16 11:27a Inlet	
#16 Acyllo Loading Rack Cabinet pump 26 ppm Photo #17 11:32	#17 Loading busses Acyllo Rack <del>ND</del> ND Photo #18 11:36	
#18 Large Filter Canisters "US Filter"	#19 <sup>2</sup> Elevated stainless Cyclones Along NE Fence BG Photo #20 11:46a	
		Bottom line.

1 866-299-5188  
VAO call 206 583 1497

Jim QIS 3/3

15

Feb. 12 request by RC for NRC  
Support for scupper valve release  
1. Sample results on Blue + Black  
Containers?

Feb 20 return for site visit  
NRC reports all is well, Cascade  
Metals all is not well " injury /  
exposure, one ~~scupper~~ alleged  
tank dumping, NRC site rep initially  
candid - then mute

Base on inspection at 10k p  
Rescreen agreed upon by NRC  
All phosphoric acid + post hydrox lines problematic  
re-cleaned, stainless All Fe rig +  
Done 2/28 Snow + holidays  
Priority →

- Field Screening + Sampling 2/27/28  
1. Starch lines ND  
2. Saponification units ND  
3. Starch reactor ND  
2 Graph reactor Yes  
3 Tank Yes  
1 carbon filters yes +  
4 4 pumps between 5 + 50 ppm

Romanian

3/7 after 8:30am left by  
Cascade Ron + Dennis

who complained of not feeling  
sofe while conducting survey.  
Ron + Dennis said that on  
pressurized line (Industrial  
Water) had sprayed them  
on 3/5 while cutting and Ron  
complained that his foot

was swelling (at wos) and  
to Dennis of a sore throat.  
On height of the 6-9 ppm AN  
slurry line discovery on the  
3/6, they were ~~sick~~ worry  
of continuing work. symptoms  
I asked them when ~~they~~  
begin and they said immediately  
after exposure. I asked why  
they did not inform me  
~~me~~ and they replied they  
didn't want to bother me.  
I asked if they had sought  
medical help and they said  
no. Ron said he had an appoint-  
ment on Sat with a doctor  
in. Ron's face, I said that

Ron's face.

They must immediately go to the hospital and after insisting twice, they agreed & stopped the scrapping operation and contacted Dowty at OR OSHA.

At approximately 10:30 AM Dennis and Ron returned from the hospital and told me their injuries were consistent with AN exposure. I had been informed by Hospital Nurse of NHC that he had witnessed the 70 cutting into a ~~choose~~ charged boiler steam pipe valve in the week and also being dosed heavily and that that water is treated with a caustic chemical to prevent scaling in the pipes and could account for their symptoms.

When I asked Dennis about this, he admitted that this had happened in addition to the industrial water dosing left on when.

3/25

Asked why they had not depressed either of the lines and he said he thought they had. I informed him that I had been told by two individuals (Eric of Pacific Coating and Milan) that the industrial water line was just city water but that I would sample it.

The cascade crew left site opposite 12 p.m.

Spoke with Savich asked me why he was being sent a P.P.P. letter, told him he should contact Cliff or Ted. Asked why the graph reactor had 8" of old dough and copolymer line were full out both green and grey. He said they should have been clean and found the copolymer showed most have been hot with AN, as he did the cliff and earlier in the month.

When we discussed Ferry of mentioned that the Superindication sheet was heavily contaminated with acidic bases and AN and he said "oh yes you should just dispose of it when turning green earlier in the month he said that AN went into an ash bin.

Worley made it to the  
sobering station

4/7

Queen Cabin 5 N  
1,300 29,000  
Ferry E  
6,300 ppm

Return to River